






Attention! Some details in the instructions may differ in terms of equipment. These are kits of several individual parts or complex designs with combined parts.






Recommendation. Install a hood (no glue)
for good and accurate positioning of parts





3



4



Remove all counter-forces in the interior of the hood.







German K.-Flak 7,7cm L/27

GM103 1/35


⊗ Rheinische Metallwaren- und Maschinenfabrik (System Ehrhardt)




7




8




9




10




11



12



13




14




Seat back. transport position

15a



Seat back. shooting position.


15b






transport position

16a



shooting position.

16b







German K.-Flak 7,7cm L/27

GM103 1/35


⊗ Rheinische Metallwaren- und Maschinenfabrik (System Ehrhardt)




Armeeabteilung of General Gaedes, Alsace, May 1915- September 1916




K-Flak 44, battle of the Somme, 1916. Hauptman Hans Jancke




Armeeabteilung of General Gaedes, Alsace, May 1915- September 1916




Freikorps, Bavarian K-Flak, 1919



A.O.K.2, K-Flak 49, 1915-1916



Zella St. Blasii, 1917-18



K-Flak 'Hanne', 1915-16



Prussian K-Flak, 1917-18

